

FMEA is a Pre-Problem Solving Methodology

- Opportunity to record what could go wrong before it does
- Take actions to prevent failures
- Both Predictive and Preventative

Root Cause Analysis (RCA) or Failure Analysis (FA) is a Post-Problem Solving Methodology

 Failure has already occurred and must be analyzed to prevent recurrence

RCA = Detection Cycle (Failure)



FMEA = Prevention Cycle (Failure)

Risk (FMEA) is used as the substitute for Failure (RCA)

www.quality-one.com